




Fig.1



Fig.2







2/17

Fig.3




Fig.4





Fig.5







3/17

Fig.6




Fig.7




Fig.8






Fig.9




Fig.10





Fig.11







1 1 100

Fig. 12




Fig. 13




Fig.14





Fig. 15










Fig.17




Fig.18






Fig.19




Fig.20




Fig.21




Fig.22




Fig.23




Fig.24

3.7 :




Fig.25




Fig.26




Fig.27

#### Approximal cleaning performance




Fig.28

### Smooth-surface cleaning performance





Fig.29

#### Plaque removal efficiency



Site inside oral cavity

Fig.30





Fig.31



16/17

Fig.32




Fig.33




Fig.34

